Project Number	2024 Capital Project Description	Category	Capital Budget	Cost to Date	Capital Cost Remaining	B- Budget IP-In Process C- Closed	Closed Project Variance to Budget
	100 - CLUBS						
P1660	Bell Billiards - New LED lights over tables	Clubs	\$10,000	\$8,000	\$2,000	С	\$2,000
P1661	Bell Billiards - New Diamond 9' table per 5 year plan	Clubs	\$10,000	\$10,712	(\$712)	С	(\$712)
P1662	Bell Lapidary - Repair/Replace Saw Ventilation System	Clubs	\$25,000	\$14,800	\$10,200	С	\$10,200
P1663	Bell Stitchers - LED Lighting	Clubs	\$30,000	\$7,130	\$22,870	С	\$22,870
P1664	Bell Woodworking - Replace all lighting with LED lights	Clubs	\$85,000	\$45,843	\$39,157	С	\$39,157
P1665	Lakeview Billiards - Replacement of table lights	Clubs	\$10,000	\$10,819	(\$819)	С	(\$819)
P1666	Lakeview Billiards - New Diamond 9' table per 5 year plan	Clubs	\$10,000	\$10,712	(\$712)	С	(\$712)
P1667	Bell Lawn Bowling - Replace seating around greens (64)	Clubs	\$45,000		\$45,000	С	\$45,000
P1668	Bell Metal - Provide overhead cover for safety cages in Alley	Clubs	\$7,500	\$3,758	\$3,742	С	\$3,742
P1669	Bell Metal - Provide LED lights for interior of club	Clubs	\$75,000	\$37,155	\$37,845	С	\$37,845
P1670	Marinette Pickleball - Change outdoor court lighting	Clubs	\$75,000	\$96,095	(\$21,095)	С	(\$21,095)
P1671	Marinette Pickleball - Add cement area with shade covers, add tables and chairs	Clubs	\$100,000	\$84,609	\$15,391	С	\$15,391
F10/1	Marinette Pickleball - Electricity to court 1&2 need power to run		\$100,000	\$84,009	\$15,591		\$15,591
P1672	Lobster Machine	Clubs	\$5,000	\$5,823	(\$823)	С	(\$823)
P1673	Marinette Pickleball - Electricity to court seating by 13 & 14	Clubs	\$5,000	\$6,786	(\$1,786)	С	(\$1,786)
F1075		-	\$492,500	\$342,243	\$150,257	0	(\$1,700)
	101 - OAKMONT		φ 4 92,300	\$572,275	<i>4130,237</i>		
P1675	Replace pool kool deck	Pool Decking	\$79,890	\$75,043	\$4,847	IP	
P1675	Clay Club - Fire risers	Fire Risers	\$41,200	\$75,045	\$41,200	IF C	\$41,200
P1677	Parking lot lighting	Lighting	\$38,192		\$38,192	c	\$38,192
P1678	Refinish interior of Oakmont Spa	Pool/Spa	\$25,000	\$90,158	(\$65,158)	c	(\$65,158)
P1678	Spa Pump w/ VFD	Pool/Spa	\$25,000	\$10,356	\$14,644	IP	(\$03,138)
P1679 P1680	Pool Pump w/ VFD	Pool/Spa	\$25,000	\$10,550	\$25,000	B	
P1680 P1681	Replace canopies @ south patio	Gazebos/Shade	\$10,030		\$25,000	C	\$10,030
P1682	Replace Hayward Pump @ pool	Pool/Spa	\$5,027		\$5,027	c	\$5,027
F1002	Replace hayward Fullip @ pool	-001/Spa	\$249,339	\$175,557	\$73,782	C	\$3,027
	102 - FAIRWAY		\$ 27 <i>9</i> ,33 <i>9</i>	\$175,557	φ 7 3,7 6 2		
P1684	Replace pool kool deck	Pool Decking	\$194,670	\$106,664	\$88,006	IP	
P1685	Replace Pentair filter @ pool	Pool Equipment	\$32,235	\$7,861	\$24,374	IP	
P1686	Spa Pump w/VFD	Pool Equipment	\$25,000	\$17,790	\$7,210	IP	
P1687	Pool Pump w/VFD	Pool Equipment	\$25,000	\$20,054	\$4,946	IP	
P1688	Replace sails @ spa	Gazebos/Shade	\$20,299	\$18,781	\$1,518	С	\$1,518
P1689	Acid feeders (2)	Pool Equipment	\$12,000		\$12,000	В	
P1690	Chlorine feeders (2)	Pool Equipment	\$12,000		\$12,000	В	
P1691	Replace Hayward Pump @ Pool	Pool Equipment	\$5,027		\$5,027	С	\$5,027
P1692	New Security	Security	\$200,000		\$200,000	В	
P1693	Add access control to Massage Rooms (2)	Security	\$12,000		\$12,000	В	
P1695	Additional parking lot lighting at east end by dog park	Lighting	\$22,500	\$17,203	\$5,297	С	\$5,297
P1697	Relocate check-in / Welcome desk into lobby area	B&I	\$150,000	\$79,540	\$70,460	IP	
		-	\$710,731	\$267,895	\$442,836		
	103 - MT. VIEW / SUNBOWL-SOFTBALL FIELD						
P1698	Mountain View - Replace Fire Sprinklers	Sprinklers	\$55,000		\$55,000	С	\$55,000
P1699	Mountain View - Fire Risers west end of auditorium	Sprinklers	\$41,200		\$41,200	С	\$41,200

Project Number	2024 Capital Project Description	Category	Capital Budget	Cost to Date	Capital Cost Remaining	B- Budget IP-In Process C- Closed	Closed Project Variance to Budget
P1700	Mountain View - Add fire sprinklers	Sprinklers	\$75,000		\$75,000	С	\$75,000
P1701	Sun Bowl - Replace Bollard Lights on Ramp	Lighting	\$35,000	\$40,025	(\$5,025)	С	(\$5,025)
			\$206,200	\$40,025	\$166,175		
D1 702	104 - LAKEVIEW/DUFFEELAND/VP LAKE	Fine Disease	± 41 200		± 41 200	-	
P1702	Lakeview - Fire Risers in the Pool Pump Room	Fire Risers	\$41,200	+10.700	\$41,200	В	
P1704	Lakeview - Replace Canopies @ pool area	Gazebos/Shade	\$25,075	\$18,768	\$6,307	IP	
P1705	Lakeview - Pool Pump w/VFD	Pool Equipment	\$25,000	\$19,946	\$5,054	B	
P1706	Lakeview - Walkway hill sidewalk repair	Concrete	\$20,000		\$20,000	В	
P1707	Lakeview - New Hot Water Heater @ Pool Pump Room	Pool Equipment	\$8,855	¢10 075	\$8,855		(4075)
P1708	Lakeview - Acid Feeders (2)	Pool Equipment	\$12,000	\$12,275	(\$275)	C C	(\$275)
P1709	Lakeview - Repair drains in columns (6 locations)	B&I Dool Equipmont	\$90,000	\$74,850	\$15,150	c	\$15,150
P1710	Lakeview - Chlorine Feeders (2)	Pool Equipment	\$12,000	\$12,589	(\$589)	c	(\$589)
P1711	Lakeview - Add ADA chair lift @ Lakeview Pool	Pool Equipment	\$18,000	\$11,458	\$6,542		\$6,542
P1712	Lakeview - Boat ramp light and camera	Security	\$10,000	\$875	\$9,125	С	\$9,125
P1713 P1716	Lakeview - Motion lights at Lawn Bowl Gazebo	Lighting Rool Docking	\$8,000	\$9,849	(\$1,849)	C C	(\$1,849)
P1/10	Lakeview - Replace Pool Kool Deck	Pool Decking	\$25,000 \$295,130	\$90,186 \$250,795	(\$65,186) \$44,335	C	(\$65,186)
	105 - SUNDIAL		\$295,150	\$230,795	\$ 44 ,555		
P1717	Sundial - Reconstruct Sewer Pit	Dlumahing	\$150,000	\$2,098	\$147,902	IP	
P1717 P1718	Sundial - Repair pool deck	Plumbing Deal Dealing	· ·	\$2,098		C	¢ 40, 420
	Sundial - Replace Bocce Ball carpet	Pool Decking	\$75,000	\$25,570 \$137,974	\$49,430	c	\$49,430
P1719 P1720	Sundial - Sidewalk concrete repair	Game Areas Concrete	\$50,000 \$50,000	\$137,974	<mark>(\$87,974)</mark> \$10,851	IP	(\$87,974)
P1720 P1721	Sundial - Fire risers Pump room for auditorium			\$39,149		B	
P1721 P1722	Sundial - Fire risers pump room	Fire Risers Fire Risers	\$41,200		\$41,200	В	
P1722 P1723	Sundial - Replace ETS Ecoflo - UV @ pool - warm water	Pool Equipment	\$41,200 \$36,623		\$41,200 \$36,623	В	
P1723 P1724	Sundial - Acid Feeders (4)	Pool Equipment	\$24,000	\$24,256	(\$256)	C	(\$256)
P1724 P1725	Sundial - Pool Feeders (4)	Pool Equipment		\$24,230		c	· · · · · · · · · · · · · · · · · · ·
P1725 P1726	Sundial - Replace ETS Ecoflo - UV @ spa - west	Pool Equipment	\$24,000 \$22,180	\$20,741	<mark>(\$2,741)</mark> \$22,180	В	(\$2,741)
P1720 P1727	Sundial - Replace ETS Ecoflo - UV @ spa - east	Pool Equipment	\$22,180			В	
P1727 P1728	Sundial - 3 new UV units				\$22,180	C	\$10,000
P1728 P1729	Sundial - Replace Hayward Pump	Pool Equipment Pool Equipment	\$10,000 \$5,027	\$21,880	\$10,000 (\$16,853)	c	(\$16,853)
P1729 P1730	Sundial - Pool Heater Stacks	Pool Equipment	\$75,000	\$21,000	\$75,000	В	(\$10,000)
P1730 P1731	Sundial - New Sand Filters	Pool Equipment	\$10,000	\$14,823	(\$4,823)	C	(\$4,823)
P1732	Sundial - LED Light Upgrade Fitness Room		\$58,000	\$24,988		c	\$33,012
P1732 P1733	Sundial - LED Light Upgrade Auditorium Hallway	Lighting Lighting	\$10,000	\$6,155	\$33,012 \$3,845	c	\$3,845
F1755	Sundar LED Light Opgrade Additionant Hallway		\$704,410	\$323,633	\$380,777	0	\$3,043
	106 - BELL		<i><i><i></i></i></i>	\$525,005	<i><i><i>q</i>300,111</i></i>		
P1735	Bell - Retrofit all parking lot lights	Lighting	\$100,000	\$28,140	\$71,860	С	\$71,860
P1736	Bell - Repair/replace cement in multiple location around center	Concrete	\$70,000	\$20,140	\$70,000	В	Ψ/ 1,000
P1730 P1737	Bell - Shuffleboard court resurface	Game Areas	\$45,000	\$4,800	\$40,200	IP	
P1738	Bell - Coat/seal wood flooring @Social Hall 1 & 2	Flooring	\$50,000	\$10,282	\$39,718	C	\$39,718
P1739	Bell - Replace Pentair filter @ pool	Pool Equipment	\$32,235	\$10,282	\$23,740	c	\$23,740
P1739 P1740	Bell - Resurface Mini Golf	Game Areas	\$80,000	\$59,035	\$20,965	c	\$20,965
P1740 P1741	Bell - Mini Golf windows upgrade	Game Areas	\$15,000	\$16,651	(\$1,651)	c	(\$1,651)
P1741 P1742	Bell - Replace doors (2) and frames on lap pool pump room	Pool Equipment	\$15,000	\$10,001	\$4,893	c	\$4,893
1 1/72		i ooi Equipment	φ 1 3,000	φ±0,±07	4-10-55	U	Ψ-1000

Project Number	2024 Capital Project Description	Category	Capital Budget	Cost to Date	Capital Cost Remaining	B- Budget IP-In Process C- Closed	Closed Project Variance to Budget
P1743	Bell - Indoor spa replace metal back door	Pool Equipment	\$7,500	\$5,753	\$1,747	С	\$1,747
P1744	Bell - Chlorine Feeders (4)	Pool Equipment	\$24,000		\$24,000	В	
P1745	Bell - Seal coat lot from 2023 install	Parking Lot	\$80,000	\$50,853	\$29,147	С	\$29,147
P1746	Bell - Re Roll of Rubaroc product by Rubber Stone	Pool Equipment	\$40,000	\$35,908	\$4,092	С	\$4,092
P1747	Bell - Add fire sprinklers (meet code)	Fire Sprinklers	\$110,000		\$110,000	С	\$110,000
P1748	Bell - New sand filters	Pool Equipment	\$7,500		\$7,500	В	
P1749	Bell - Acid Feeders (4)	Pool Equipment	\$24,000		\$24,000	В	
P1750	Bell - Replace shades - walkway between library, visitors center	Gazebos/Shades	\$10,000	\$5,039	\$4,961	С	\$4,961
P1752	Bell - Remodel Tennis locker room/restrooms	B & I	\$250,000	\$271,844	(\$21,844)	IP	
			\$960,235	\$506,907	\$453,328		
	107 - MARINETTE	_					
P1753	Marinette - Demo & Install new running track	Game Area	\$120,000	\$129,072	(\$9,072)	С	(\$9,072)
P1754	Marinette - Replace canopies @ west and south PB Courts	Gazebo/Shade	\$47,762	\$5,811	\$41,951	С	\$41,951
P1755	Marinette - Spa pump w/ VFD	Pool Equipment	\$25,000	\$22,942	\$2,058	С	\$2,058
P1756	Marinette - Pool pump w/ VFD	Pool Equipment	\$25,000	\$25,693	(\$693)	С	(\$693)
P1757	Marinette - Replace canopies @ pool heater area	Gazebo/Shade	\$9,552		\$9,552	С	\$9,552
P1758	Marinette - Acid feeders (2)	Pool Equipment	\$12,000		\$12,000	В	
P1759	Marinette - Chlorine feeders (2)	Pool Equipment	\$12,000		\$12,000	В	
P1760	Marinette - Automatic door operators to 2 fitness room door	B&I	\$15,000	\$11,247	\$3,753	С	\$3,753
P1761	Marinette - Access control to Pickleball storage room	B & I	\$6,000		\$6,000	С	\$6,000
P1762	Marinette - Repair uneven concrete and asphalt between pump room	Comenate	¢1 E 000	¢C 533	t0 467	С	¢0.467
P1702	and barn	Concrete _	\$15,000 \$287,314	\$6,533 \$201,298	\$8,467 \$86,016		\$8,467
	109 - GRAND		\$207,JI4	\$201,298	\$00,010		
P1764	Grand - Gate off street entrances	Fencing	\$100,000	\$44,958	\$55,042	IP	
11/04	Grand - Gate on street entrances		\$100,000	\$44,958	\$55,042	п	
	141 - GEORGE'S CAFE (Lakeview Lanes)		<i>4100</i> ,000	\$44,556	<i>455,642</i>		
P1773	George's Café - Replace ice machine and bin	Café Equip	\$10,000		\$10,000	С	\$10,000
11//5	deorge 5 eare - Replace lee machine and bin		\$10,000	\$0	\$10,000	0	\$10,000
	200 - BOWLING		410,000	4 0	<i><i><i></i></i></i>		
P2025	Lakeview Lanes - Replace Fire Sprinklers	Fire Sprinkler	\$55,000	\$0	\$55,000	С	\$55,000
P2026	Lakeview Lanes - Add Fire Sprinklers	Fire Sprinkler	\$50,000	40	\$50,000	c	\$50,000
P2027	Lakeview Lanes - Pave (Resurface) Parking lot	Paving	\$25,000	\$71,000	(\$46,000)	c	(\$46,000)
P2028	Lakeview Lanes - Fire Risers	Fire Sprinkler	\$41,200	\$71,000	\$41,200	c	\$41,200
12020			\$171,200	\$71,000	\$100,200	0	<i>ψ</i> 11/200
	322 - GOLF		+/	+,	+/		
P3180	North Maintenance - Add fire sprinklers (meet code)	Golf	\$175,000		\$175,000	С	\$175,000
P3181	North Golf Course Pro Shop/Snack Shop - New security	Golf	\$75,000		\$75,000	В	<i><i><i>q</i>₁, <i>bf</i>₀, <i>b</i>₀, <i></i></i></i>
P3182	Quail Run Maintenance - Add fire sprinklers (meet code)	Golf	\$175,000		\$175,000	C	\$175,000
P3184	Quail Run Golf Course -replace awnings @ patio	Gazebo/Shade	\$7,101		\$7,101	C	\$7,101
P3186	Lakes Pro Shop - LED Light Upgrade	Lighting	\$50,000	\$10,230	\$39,770	C	\$39,770
P3187	Lakes Pro Shop - Golf Cart Fleet replacemnet/addition	Vehicles	\$100,000	+_0,_00	\$100,000	В	+00///0
P3188	Riverview Maintenance - Add Fire Sprinklers (meet code)	Fire Sprinklers	\$175,000		\$175,000	C	\$175,000
P3189	Riverview Maintenance - Wash rack replacement	Golf	\$60,000		\$60,000	c	\$60,000
P3190	Riverview Pro Shop - Resurface parking lot	Paving	\$40,000	\$19,677	\$20,323	C	\$20,323
			+ 10/000	+=0,000	+=0,020	-	+20,020

Project Number	2024 Capital Project Description	Category	Capital Budget	Cost to Date	Capital Cost Remaining	B- Budget IP-In Process C- Closed	Closed Project Variance to Budget
P3191	Willow Pro Shop - Lighting for Parking Lot	Lighting	\$150,000	\$63,351	\$86,649	IP	
P3192	Willow Maintenance - replace awnings	Gazebo/Shade	\$7,523	\$22,701	(\$15,178)	С	(\$15,178)
P3193	All Golf Courses - Golf Equipment replacement	Golf Equip	\$840,000	\$220,352	\$619,648	IP	
			\$1,854,624	\$336,310	\$1,518,314		
	FITNESS EQUIPMENT						
P1683	Fitness Equipment Replacements/Upgrades (Oakmont)	Fitness Equip	\$311,410	\$174,264	\$137,146	IP	
			\$311,410	\$174,264	\$137,146		
54674	VEHICLES	A 11	+270 270		(+00,000)		(+00, 200)
P1674	RCSC Replacement Vehicles	Operations	\$370,270	\$459,656	(\$89,386)	С	(\$89,386)
P1715	Lakeview - Replace Utility Cart	Vehicles	\$16,000	\$12,953	\$3,047	С	\$3,047
P1765	Grand - Replace utility cart	Vehicles	\$16,000	+172 600	\$16,000	С	\$16,000
			\$402,270	\$472,609	(\$70,339)		
	Capital for 2024	1	\$6,755,363	\$3,207,495	\$3,547,868		\$1,352,489
	Unbudgeted			Cost To Date	Budget		
P1774	Bell - LED Lighting in Fitness Room	B & I	\$0	\$11,250	\$11,250	С	(\$11,250)
P1775	New Clubs Office	B & I	\$0	\$55,232	\$55,232	С	(\$55,232)
P1776	Mountain View - Mini Golf Carpet	B&I	\$0	\$63,037	\$63,037	С	(\$63,037)
P1777	Duffeeland Dog Park - Key FOB Entry System Metal Gates	B&I	\$0	\$12,989	\$12,989	С	(\$12,989)
P1778	Mountain View - Pool Equipment Canopy	B&I	\$0	\$42,002	\$42,002	С	(\$42,002)
P1779	Grounds - Dump Truck	Vehicles	\$0	\$98,534	\$98,534	С	(\$98,534)
P1781	George's Café Lakeview - Replace Swamp Cooler	B&I		\$5,255	\$5,255	С	(\$5,255)
P1782	Bell - Central Plant Rebuild Condenser Pump and Replace Valves	B & I	\$0	\$9,995	\$9,995	С	(\$9,995)
P1783	Sundial - Stage Repairs	B & I	\$0	\$59,898	\$46,000	С	(\$59,898)
P1784	Lakeview Board Room Audio Visual Makeover	B&I		\$35,760	\$32,400	С	(\$35,760)
P1785	Bell - Outdoor Spa Pentair Pool Pump	B & I	\$0		\$25,447	IP	
P1786	2024 Ford Transit Van	B & I		\$52,584	\$52,584	С	(\$52,584)
P1787	Oakmont Lawn Bowl Shade Structure	B & I	\$0	\$53,073	\$90,000	С	(\$53,073)
P1788	Sundial - MAC room Update	B & I	\$0	\$24,776	\$24,000	С	(\$24,776)
P1789	Fairway Lights for Walking Track	B & I		\$23,500	\$24,500	С	(\$23,500)
P1790	Marinette - Front Dest Extension Project	B & I	\$0	\$13,535	\$84,000	С	(\$13,535)
P1791	Media Studio Preliminary Equipment		\$0	\$23,103	\$24,000	IP	
P1792	Bell - Café Cooler/Freezer Outdoor Fenced Area	B & I	\$0	\$50,523	\$51,038	С	(\$50,523)
P1793	Oakmont FA Station AC Unit	B & I			\$10,500	IP	
P1794	Redesign RCSC Website		\$0	\$187,644	\$343,350	IP	
P1795	George's Café HVAC Unit	B&I		\$17,871	\$17,872	С	(\$17,871)
P1796	Marinette Broken Irrigation Line under Pavement	B&I	\$0	\$9,581	\$15,000	С	(\$9,581)
P1797	South Maintenance - New HVAC	B&I	\$0	\$9,227	\$9,227	С	(\$9,227)
P2029	Bell Lanes - Sewer Line	Plumbing	\$0	\$33,410	\$33,410	С	(\$33,410)
P2030	Lakeview Lanes - Sewer Line	Plumbing	\$0	\$23,500	\$23,500	С	(\$23,500)
P3194	Pumps and Well Replacement	Wells	\$0	\$80,355			
	Total		_	\$996,635	\$1,205,123		(\$705,533)